

Date: August 25, 2020
 To: Sergeant J. G. Housden, PhotoSafe Program Supervisor
 From: David A. Keisel, PhotoSafe Program Investigator

Intersection Location: Baxter Rd at Independence Blvd

On Sight Evaluation:

Yes No

- 1- Traffic Signal heads, poles, and back plates in place and not damaged.
- 2- Traffic Signal lights working properly and visible
- 3- Photo enforcement warning signs in place at monitored approaches
- 4- Pavement markings (stop bar, crosswalks, etc.) are in good condition
- 5- Enforcement equipment in place and not damaged
VAB030 knocked down 8/21/2020 DR# 2020-00027419
- 6- Vegetation is NOT obstructing view of traffic signal, cameras, or warning signs

Violation Enforcement Criteria:

Yes No

- 1- Length of Yellow Light is at the VDOT approved standard of 6.2 seconds
 - Left turn Only (35 mph 4.7 seconds; 45 mph 6.2 seconds; 50 mph 6.9 seconds)
 - 4.8 seconds
 - Straight & Right Turn (35 mph 4.1 seconds; 45 mph 4.8 seconds; 50 mph 5.2 seconds)
- 2- Enforcement occurs at or after the .5 second amnesty period.

David A. Keisel

Signature - PhotoSafe Program Coordinator