

Date: May 26, 2020
To: Sergeant J. G. Housden, PhotoSafe Program Supervisor
From: David A. Keisel, PhotoSafe Program Investigator

Intersection Location: Independence Blvd at Bonney Rd

On Sight Evaluation:

- 1- Traffic Signal heads, poles, and back plates in place and not damaged.
2- Traffic Signal lights working properly and visible
3- Photo enforcement warning signs in place at monitored approaches
4- Pavement markings (stop bar, crosswalks, etc.) are in good condition
5- Enforcement equipment in place and not damaged
6- Vegetation is NOT obstructing view of traffic signal, cameras, or warning signs

Violation Enforcement Criteria:

- 1- Length of Yellow Light is at the VDOT approved standard of 4.8 seconds
2- Enforcement occurs at or after the .5 second amnesty period.

David A. Keisel
Signature - PhotoSafe Program Coordinator