

Date: July 30, 2020
 To: Sergeant J. G. Housden, PhotoSafe Program Supervisor
 From: David A. Keisel, PhotoSafe Program Investigator

Intersection Location: Independence Blvd at Bonney Rd

On Sight Evaluation:

	Yes	No
1- Traffic Signal heads, poles, and back plates in place and not damaged.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2- Traffic Signal lights working properly and visible	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3- Photo enforcement warning signs in place at monitored approaches	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4- Pavement markings (stop bar, crosswalks, etc.) are in good condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5- Enforcement equipment in place and not damaged	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6- Vegetation is NOT obstructing view of traffic signal, cameras, or warning signs	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Violation Enforcement Criteria:

	Yes	No
1- Length of Yellow Light is at the VDOT approved standard of <u>4.8 seconds</u> (35 mph 4.1 seconds; 45 mph 4.8 seconds; 50 mph 5.2 seconds)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2- Enforcement occurs at or after the .5 second amnesty period.	<input type="checkbox"/>	<input type="checkbox"/>

David A. Keisel

Signature - PhotoSafe Program Coordinator