PD424 (0820)

PhotoSafe – Monthly Evaluation of Red Light Camera Intersections

Date: August 25, 2020
To: Sergeant J. G. Housden, PhotoSafe Program Supervisor
From: David A. Keisel, PhotoSafe Program Investigator

Intersection Location: Independence Blvd at Bonney Rd

On Sight Evaluation:	**Yes**	**No**
1- Traffic Signal heads, poles, and back plates in place and not damaged.	☒	☐
2- Traffic Signal lights working properly and visible	☒	☐
3- Photo enforcement warning signs in place at monitored approaches	☒	☐
4- Pavement markings (stop bar, crosswalks, etc.) are in good condition	☒	☐
5- Enforcement equipment in place and not damaged	☒	☐
6- Vegetation is NOT obstructing view of traffic signal, cameras, or warning signs	☒	☐

Violation Enforcement Criteria:	**Yes**	**No**
1- Length of Yellow Light is at the VDOT approved standard of 6.2 seconds	☒	☐
• Left turn Only *(35 mph 4.7 seconds; 45 mph 6.2 seconds; 50 mph 6.9 seconds)* 4.8 seconds	☒	☐
• Straight & Right Turn *(35 mph 4.1 seconds; 45 mph 4.8 seconds; 50 mph 5.2 seconds)*		
2- Enforcement occurs at or after the .5 second amnesty period.	☐	☐

David A. Keisel

Signature - PhotoSafe Program Coordinator